REVISEO 5-7-87 UNIT Cable 2293287-503 TQ-14-86 SHUTTLE COTY DWG NO. и 4.23.1 FMEA NO. CRITICAL LIEMS LIST ISSUED SHEET CRITICALITY 2/18 FAILURE EFFECT FAILURE MODE AND RATIONALE FOR ACCEPTANCE ON END ITEM CAUSE No video or control Loss of LOC 2 DESIGN FEATURES for locations The N4 PTU cable is a 44-inch long, 25-wire assembly terminated by 17 pin connectors at each end. The video and sync/cmd wires are shielded Twinax shielded and twisted pairs: Open regulaino LOC 2. of #24 wire. The cable connects the TVC and PTU. Connector types KJG6E14N355N18 have been selected. Worst Case: No PIU control of elbow The cable design is taken from the successfully flown Apollo program. The design is a camera to permit arm cable-connector assembly in which the wire terminations are protected from excessive flexture at the joint between the wire and the connector terminal. The load stowage. concentration is moved away from the conductor connection and distributed axially along the length of the conductors encapsulated in a potted-taper profile. This technique also protects the assembly from dirt and entrapped moisture which could cause problems in space. The cable and its components meet the applicable requirements of MASA, Hilitary and RCA specifications. These requirements include: General/Rechanical/Electrical Features Design and Construction **Haterials** Terminal Solderability Environmental. Qualification Harking and Serialization Traceability and Documentation à

REVISED 5-7-87 UNIT Cable 2293287-5U3 SHUTTLE CCTV DM8 VOT H 4.23.1 FMEA NO. [5SUEO 10-14-85 CRITICAL ITEMS LIST SHEET CHITICALITY 2/ JR FATLURE MODE AND FAILUNE EFFECT RATIONALE FOR ACCEPTANCE ON EMD ITEM CAUSE No video or control iss of LOC 2 **QUALIFICATION TEST** for locations Qualified by 1.) similarity to previous successful space programs and 2.) by use during)en requiring LOC 2. qualification tests of CCTV IRUS. ACCEPTANCE TEST **Horst Case;** No PIU control of elbam The cable acceptance test consists of an ohmmeter check to assure that each wire camera to permit arm connection is present and intact. Results are recorded on data sheets. stawane. OPERATIONAL TEST The following tests verify that CCTV components are operable and that the commands from the PNS (AZA) panel switch, through the RCU, through the sync lines to the Camera/PTU. to the Camera/PTU command decoder are proper. The tests also verify the comera's ability to produce video, the VSU's ability to route video and the monitor's ability to display video. A similar test verifies the MDM command path. Pre-Launch on Orbiter Test/In-flight Test Power CCTV System. Select a monitor via the PHS panel, as destination and the camera under test as Send "Camera Power On" command from PHS panel. Select "External Sync" on monitor. Observe wideo displayed on monitor. If video on monitor is synchronized (i.e., stable master), then this indicates that the camera is receiving composite symc from the RCH and that the camera is producing synchronized video. Send Pan, Illt, Focus, Zoom, ALC, and Gamma commands and visually (either via the monitor or direct observation) verify proper operation. Select Doynlink as destination and camera under test as source. Observe wides routed to downlink. Send "Camera Power Off" command via PHS panel. Repeat Steps 3 through 9 except issue commands via the MDH command path. This proves that the ECTV couldment is operational if video is satisfactory.

OC D

0.00

REVISED 5-7-87

FMEA NO. <u>N.4.23.)</u> CRITICALITY 2/1R		SHUTTLE CCTV CRITICAL ITEMS LIST	DMG NO. 2293207-503 1SSUED 10-14-86 SHEET J OF 5
FAILURE MODE AND FAICURE EFFECT CAUSE ON END ITEM		RATIONALE FOR ACCEPTANCE	
Loss of LOC ? Open	Ho video or control for locations requiring LOC 2. Norst Case: No PTU control of elbow camera to permit arm stowage.	Procurement Control - Wire, connectors, solder, and suppliers which meet the requirements set for Plan Work Statement (WS-2593176). Incoming Inspection & Storage - trooming Quality materials and parts. Results are recorded by lot control numbers for future reference and traceably Naterial Controlled Stores and retained under specification is required. Mon-conforming material (MRB) disposition. (PAI-307, PAI 19C-53). Assembly & Test - Prior to the start of assembly, by stock room personnel as the items are accumulated again by the operator who assembles the as-built-parts-list (ABPL). Specific instructions are given in assembly draw called out in the Fabrication Procedure and Record Process Standard crimping flight connector contains plicing of standard interconnecting wire using if Process Standard marking of parts or assemblies a material and test procedure (TP-AT-22932H/). Quality is a completion of key operations. Preparation for Shipment - When fabrication and it packaged &ccording to 7780746, Process Standard All related documentation including assembly draw is gathered and held in a ducumentation folder as assembly. This Folder is retained for reference.	inspections are made on all received that and retained in file by drawing and silty. Accepted items are delivered to ecified conditions until cable is are held for Material Review Board. all items are verified to be correct ated to form a kit. The Items are kit by checking against the ing material applicable documents and (FPR-2293287). These are 2280800 acts, 2280801 - Process Standard in-line Raychem solder sleeves, 2280876 - with epoxy colors, 2280876. Potting ality and DCAS inspections are performed test is complete, the cable assembly is for Packaging and Handling Guidelines. Wings, Parts List, ABPL, Test Data, etc. ssigned specifically to each cable
	1	· ·	

REVISED 5-7-87 UNIT Cab Te 2293287-503 DHG NOT SHUTTLE CCTV CRITICAL [TEMS LIST H 4.23.1 FMEA NO. 155HED 10-14-86 SHEET CRITICALITY 2/1R FATEURE MODE AND Cause FATLURE EFFECT ON END ITEM RATIONALE FOR ACCEPTANCE No video or control FAILURE HISTORY Loss of LOC 2 for locations There have been no reported failures during RCA testing, pre-flight or flight. Open requiring £00 2. Morst Case: No PTU control of elbow camera to permit arm stowage.

·			REVISED 5-7-87
FMEA NO. N 4.23.1 CHITICALITY 2/18		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT Cable OMG MO. 2293287-503 1\$SHED 10-14-HB SHEET 5 DF 5
FATEORE MIDE AND	FAILURE EFFECT ON CAD ITEM	RATIONALE FOR ACCEPTANCE	
Loss of LOC 2 Open	No video or control for locations requiring LOC 2. Verst Case: No PIU control of elbow camera to permit arm stowage.	Loss of ability to position the Elbow camera. elbow camera physically interferes with a paylo payload bay door cannot be closed. Loss of crecent ACTIONS Perform EVA to reposition the elbow camera, use jettison the RMS. CREW TRAINING Crew should be trained in contingency EVA and FMISSION CONSTRAINT Do not manifest Elbow camera for any flight who interfere with each other (for any pan or tilt not change the camera position until the interference of the camera position until the c	ew and vehicle. RMS motion to reposition the camera, or RMS operations procedures.` ere the payload and the elbow camera can angle). If the camera must be flown do